

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/PWD Dt. 23-01-1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub-District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

ST. MARY'S BETHANY PUBLIC SCHOOL  
KAYAMKULAM, MAVELIKKARA

G.F. 1172.00 m<sup>2</sup>  
F.F. 1172.00 m<sup>2</sup>  
SC 54.00 m<sup>2</sup> Total 2398.00 m<sup>2</sup>

5. Period for which the certificate is issued
6. Nature of defects, if any
  - a) Foundation and basement
  - b) Superstructure
  - c) Doors and Windows
  - d) Wood work wrought and put up
  - e) Roof
  - f) Flooring
  - g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner

2023-2024

Nil

8. Whether maintenance works have been done properly
9. Whether the structure is sound or not for conducting classes

yes  
The structure is sound for conducting classes under normal weather conditions.

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

## CERTIFICATE

certified that the school building was inspected by me on 04/07/2023 and found to be fit / unfit to conduct classes, for the period 2023-2024 for the reasons stated above.

Place: Kayamkulam  
Date: 04/07/2023



*[Signature]*  
Assistant Engineer

REGHU P.  
Asst. Engineer  
Kayamkulam Municipality